## Illinois Environmental Protection Agency 2

2200 Churchill Road, Springfield, Illinois 62706

EPA Region 5 Records Ctr.

350671

## MEMORANDUM

DATE:

April 13, 1978

TO:

Division File

FROM:

John Taylor

SUBJECT:

Tazewell County - LPC 17981801 - Washington/Weaver

The Weaver Trucking Service site was inspected on April 13, 1978, by Rene' Van Someren and John Taylor. The site was observed to be in violation of the Rules, and, to some extent, Pollution Control Board Order No. PCB 75-2.

The site has been closed since June 29, 1974, but it appears that final covering was never completed. A few test holes dug in the northern half of the site revealed that the cover depth was less than adequate. Severe erosion has uncovered some small amounts of refuse along the northern slope of the site and many leachate seeps were observed in this area.

Along the east edge of the site, toward the northeastern corner, leachate was observed leaving the site and entering a small stream bed. Some recovering is needed in this area.

The Board Order, PCB 75-2, does not actually order the respondents to finally cover the site. Apparently, the Order was based on the assumption that the site was covered to a great degree and that only remedial work was needed in the northwestern and northeastern corners of the site. Most of the stipulated proposal for settlement dealt with problems at the south end of the site which were taken care of as agreed. The only part of the Order that was not complied with was the following of Rule 318. There appears to be little reason for enforcement of the Order in Circuit Court as the main problem, final cover, is not dealt with in the Board's Order.

More borings are needed at this site to further identify the extent of the final cover violation. A grid system should be set up to make a systematic check of cover depth on the site. After this, a compliance conference should be scheduled to determine a plan to finally cover and close out this site.

JT:mat/3372,7

cc: Land FOS Manager Central Region

## ENVIRONME: L PROTECTION AGENCY STATE O' LLINOIS $\frac{L}{1} \stackrel{P}{C} \stackrel{F}{E} \stackrel{C}{C} \stackrel{O}{=} \frac{5}{6} \stackrel{5}{=} \stackrel{C}{(9)}$

•			<b>8</b> ) ( <b>9</b> )			V
	INSPECTION REPORT -	SITE INVENTOR	Y NO. 1778	1801		
			(11)	(18)		
lazewell	Co L.P.C.	Regio	n #		STTTZ	
\. / h. E.			(19)	(2)	•	(25)
Washing The	Responsi	1a Party)		Letter Sent	(ies or M	(26)
Samples Taken: Y	C NO CONTRACTOR	ne: From O 1	: 2 A P m	Weather _c	-a- F0-6	
Ground Water() Sur	face() Other()		: O O P =		EUP SUE	<del></del>
	ON No () In		SAFE	Inspector	.1 P	7
	- , , ,			•	(27)	(29)
Previous Inspection	10-25-76 Previ	ous Correspond	ence 11-16-76	Site Oper	n: Yes()	No 🛇
OPERATIONAL STATUS:	TYPE OF OP	ERATION:			RIZATION:	
Operating	( ) Sanitary L	andfill 👀		E.P.A	. Permit (	
Temporarily Closed	() Random Dumj	()	Salvage ( )	Varia	ice (	
Closed Not Covered			A.C.D. ( )	21(e)	(	
Closed and Covered	( ) Quantity R	eceived Daily(				( )
	·	più	(30)	Illega	<b>a</b> 1 (5) (	<b>∞_5</b> _
		SITE EVALUAT	ION			(31)
Leachate: Ponded or	n site (X)	• • • • • •		• • • • •	• • • •	32
	on site (X)					33 X
Seeping	(X)	• • • • • •			• • • •	34 <b>X</b>
Evidence	of past flows (X) .		· · · · · · · · · · · · · · · · · · ·	• • • • •		35 🗶
Ubserved	garbage( ) refuse( ) ering surface water	in standing	water (x)	& ECEIV	/FD	36
riow ente	ring surface water	(3)	• • • • • • •		AP.	37 5
riow lear Observation Observation	ring site (1-3)	• • • • • •	• • • • • •	14AV 5 10	278	38.
	md fire (5)					39
Prof dones	of recent open burni	· · · · · · · · · · · · · · · · · · ·	• • • • • •	EDA [		41
						42
Daily Cover: Not no	lent fire protection covided on previously	denogited re	fuse (5)	STATE OF THE		43 —
	ided on previous open					44
	e depth over entire					45
	e depth over only a					46
	Inadequate depth in					47
	uate depth in some a					48 3
	e depth over entire					49
	lays after area closu					
	ervised (3)					
Refuse not deposi	ted at toe of slope	()				
	ling and compacting		\			
	able equipment on si		d () <del>} (</del> 2 ea.	2-8)		52
	unsatisfactory ( )	-	/			
	, dust nuisance obse					53
	rder Violation no					54 2
	( I not permitted (5					55
	estriction() Site of					56
	ter( ) Sanitary Faci					57
	perator() Others()				• • • •	58
	d():Improperly cond					59
	rs observed ( ) (1-					60
Animal feeding ob	served ( ) (1-3) .		• • • • • •	• • • • •	• • •	61
General Compliance (	) Imp	rovement Need	ed 💢	Improvement	Observed	()
Signature of operato	r does not necessari	ly imply agree	ement with the	above noted	observati	ons.

Signature .

Owner/Operator

LPC-5 (Rev. 6-75-500)